Work Order I	D 61513
--------------	---------

Monday, August 30, 2010 9:16:29 AM

Page 1

Item ID:

D3823-1KIV

Accept

Setup Start



Revision ID:

Item Name:

Overhead Rear, LH-Ivory

Start Date:

8/30/2010

Start Qty: 1.00

Req'd Qty: 1.00

Cust Item ID: Customer:

Reference:

Approvals:

Date: 26-8-30 Tooling:

SPC (Y/N):

Date: Date: Run

Start Stop

Stop



Sequence ID/ **Work Center ID**

Required Date: 9/6/2010

Operation Description

Dry material

Date:

Set Up/ **Run Hours** Tool ID

Tool # Plan Code

Accept Qty

Reject Reject Qty Number

Insp. Stamp

Draw Nbr

Revision Nbr

QC:

D3823

100

Res (

HandThermo

Hand Finishing Thermoforming

Memo

1-Cut Sheet to required Blank size

0.00

0.00

105

HandThermo

Hand Finishing Thermoforming

Memo

Dry Sheet as per/QSI022 KYDEX

Temp:

0.00

0.00

W/0:6/	1513	WORK ORDER CHAN	GES				
DATE	STEP	Pern. hange	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
101/018	100	ADD in correct confirmation in Leader box	Dh.	10/10/14			soluolis
					•		

Part No: <u>D3823-1 KIV</u>	PAR #:	Fault Category:	NCR: Yes No DQA:	Date:
Resolution:		Disposition:	QA: N/C Closed:	Date:

	WORK ORDER NON-CONFORMANCE (NCR)										
	Description of NC		Corrective Action Section B	Verification	Approval	Approval					
SIEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspector				
			, .								
	STEP	STEP Description of NC Section A	STEP Description of NC Section A Initial Chief Eng	STEP Description of NC Section A Initial Chief Eng Corrective Action Section B Action Description Chief Eng	STEP Description of NC Section A Chief Eng Chi	STEP Description of NC Section A Chief Eng Corrective Action Section B Verification Section C Chief Eng Ch	STEP Description of NC Section A Initial Chief Eng Chief				

Work Order ID 61513

Monday, August 30, 2010 9:16:29 AM



Page 2

Item ID:

D3823-1KIV

Accept

Setup Start



Revision ID:

Item Name: Overhead Rear, LH-Ivory

Start Date:

Required Date: 9/6/2010

8/30/2010

OC:

Start Qty: 1.00

Operation

Description

Req'd Oty: 1.00



Date:____

Cust Item ID: Customer:

Tool ID

Reference:

Approvals:

Process Plan: ____ Date:

Tooling: **SPC (Y/N):**

Set Up/

0.00

0.00

Run Hours

Date:

Date:

Tool # Plan

Code

Start

Reject

Qty

Run

Stop

Reject

Number

Stop



Insp.

Stamp

Sequence ID/

Work Center ID

110

Thermoform

Thermoforming Machine

Memo

1-Machine Set-Up

2-Pre-heat Tool to required temp.

3-Thermoform as per Dwg and Folio #FTA030using tool DT9112

Dwg Rev:-Folio Rev:

QC2- Inspect parts off machine FAI/FAIB

120

Memo

0.00

0.00

Quality Control

Visually inspect part for proper formation and texture

Accept

Qty

10/10/07

130

Quality Control

QC8- Inspect parts - second check

0.00

Memo

0.00

W/O:		WORK ORDER CHANGES											
DATE	STEP	PRO	OCEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector				
								,					
									{ 				
							<u> </u>						
Part No		PAR #:											
	Re	esolution:	Dispositio	n:	QA: N/C C	losed:		Date: _					
NCR:		,	WORK ORD	ER NON-CONFORMA	NCE (NCI	R)							
DATE	STEP	Description of NC		Corrective Action Section B			ation	Approval	Approval				
DATE	OIL.	Section A	Initial Chief Eng	Action Description Chief Eng	Sign of Date		on C	Chief Eng	QC Inspector				
					-	,							
					; ; ;								

Wo	rk (Ord	er I	D 6	151	13
* * •		O I U	VI 1	$\boldsymbol{\nu}$	Jυ.	L

Monday, August 30, 2010 9:16:29 AM



Page 3

Item ID:

D3823-1KIV

Accept



Setup Start

Stop



Revision ID:

Item Name:

Overhead Rear, LH-Ivory

Start Date:

8/30/2010

Start Qty: 1.00

Req'd Qty: 1.00



Cust Item ID: Customer:

Reference:

Approvals:

Process Plan: Date: Tooling:

QC: _____ Date: ____

SPC (Y/N):

Date:

Date:

Run Start

Sequence ID/

Work Center ID

140

HandThermo

Hand Finishing Thermoforming

Required Date: 9/6/2010

Operation Description

Set Up/ **Run Hours**

0.00

0.00

Memo 1-Trim to finished dimensions as per Dwg Tool ID

Tool # Plan Code

Accept Qty

Reject Reject Qty Number

Stop

Insp. Stamp

150

QC

Quality Control

QC2- Inspect parts off machine FAI/FAIB

Complete FAI document

QC5- Inspect part completeness to step on W/O

0.00

0.00

160

Memo

Memo

6 10/10/13

0.00

Quality Control

	. Johaco .									
W/O:			WO	RK ORDER CHAN	GES					,,
DATE	STEP	PRO	IGE	Ву	C	ate	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
v.										
Part No			Fault Categ	NCR: Yes No DQA: Date:						
	Res	solution:	Disposition	•	QA: N/C	Close	ed:		Date: _	····
NCR:			WORK ORDE	R NON-CONFORM	IANCE (N	CR)				
DATE	STEP	Description of NC	ļ	Corrective Action Section B Verificatio				ation	Approval	Approval
		Section A	Initial Chief Eng	Action Description Chief Eng		n & ate	Section		Chief Eng	QC Inspector
ı										

Work Order ID 61513

Monday, August 30, 2010 9:16:29 AM



Page 4

Item ID:

D3823-1KIV

Accept



Setup Start

Stop



Revision ID:

Item Name:

Overhead Rear, LH-Ivory

Start Date: 8/30/2010

Start Oty: 1.00

Required Date: 9/6/2010 Req'd Otv: 1.00

Operation

Description



Cust Item ID:

Customer:

Reference:

				_
A	nn	ro	va:	6.

Process Plan:

Date:

Tooling:

Date:

Run Start



OC:

Date:

SPC (Y/N):

Set Up/

Run Hours

Date:

Stop



Sequence ID/ Work Center ID

170

Packaging Packaging

Memo

Identify as per dwg & Stock Location:

0.00

0.00

Tool ID

Tool # Plan

Accept Qty Code

Reject Reject Qty

Insp.

Number Stamp

180

QC

Quality Control

QC21- Final Inspection - Work Order Release

0.00

Memo

0.00

10/10/14 751 MF 10/14

W/O:			WO	RK ORDER CHANG	3FS					
DATE	STEP	PRO	OCEDURE CHAI		В	у	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
-										
Part No	•	PAR #:	Fault Cate	jory:	NCR: `	res N	lo DQ	A :	Date:	
	Res	olution:	Disposition	l:	QA: N/	C Clo	sed:		Date:	
NCR:			WORK ORDE	R NON-CONFORM	ANCE (N	ICR)				
DATE	STEP	Description of NC		Corrective Action Sec Action Description				ation	Approval	Approval
DATE	Section A		Initial Chief Eng		Date			Chief Eng	QC Inspector	
		,								
									1	
						·				
	1		1				1		1	ŀ

Picklist Print

Monday, August 30, 2010 9:16:33 AM

Work Order ID: 61513

Parent Item:

D3823-1KIV

6185 KYDEX .080"

Parent Item Name: Overhead Rear, LH-Ivory



Start Date: 8/30/2010

Required Date: 9/6/2010

Start Oty: 1.00

Loc Code

Required Qty: 1.00

Comments:

IPP RevA: New issue DD verified by:EC

Add Step 105 Dry Material 10/04/21 DL

Ipp Rev. B

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Primary Item Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
MKYD6185S.080-P3-		Purchased	No		100	sf	588.8500	11.15	11.1555	8		-

Loc Oty

588.85

588.85

Page 1

Location


109703

Dart Aerospace	e Ltd
----------------	-------

	•											
W/O:			WORK ORDER CHANGES									
DATE	STEP	PR	OCEDURE CHAI	IGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
												
Part No: PAR												
	Re	solution:	Disposition	li	QA: N/C	Closed:		Date: _				
NCR:			WORK ORDE	R NON-CONFORM	ANCE (NC	R)						
DATE	STEP	Description of NC		Veri			Approval	Approval				
DATE S	OILI	Section A	Initial Action Des Chief Eng Chief E		Sign Dat	& Sec	tion C	Chief Eng	QC Inspector			


DART AEROSPA	ACE LTD			Wo	rk Order:	61513		
Description: Rear C	Overhead, LH			Part Number:		D3823-1KIV/KGY		
nspection Dwg: D3	3823 Rev: C					Page 1 of 1		
	FIRST A	RTICLE INSP	ECTION	CHECK	LIST			
	X	First Article		Prototyp	e	•		
	T	HERMOFORM	IING SE	CTION				
Description			Accept	Reject	Method of Inspection	Comments		
nside Radii less tha	n		V					
Shape Definition								
Texture Retention				/				
Material imperfection scratching	ns such as bumps,	, cracks, voids,						
	····							
			·					
			:					
Measured by:		1			D-4-			
	W W				Date	10/10/87		
	W W	TRIMMING	SECTIO)N	Date	10/10/87		
Drawing		TRIMMING Actual			Method of			
	Tolerance		SECTION Accept	N Reject		Comments		
Drawing	Tolerance Min	Actual			Method of			
Drawing Dimension		Actual	Accept		Method of			
Drawing Dimension 0.5	M in	Actual	Accept		Method of			
Drawing Dimension 0.5 0.44 1.75 0.045	Min Min	Actual Dimension O.516' O.416' J. 8'6" O.068'	Accept		Method of			
Drawing Dimension 0.5 0.44 1.75	Min Min Min	Actual Dimension OSC O46 1.56	Accept		Method of			
Drawing Dimension 0.5 0.44 1.75 0.045	Min Min Min Min	Actual Dimension O.516' O.416' J. 8'6" O.068'	Accept		Method of			
Drawing Dimension 0.5 0.44 1.75 0.045	Min Min Min Min	Actual Dimension O.516' O.416' J. 8'6" O.068'	Accept		Method of			
Drawing Dimension 0.5 0.44 1.75 0.045	Min Min Min Min	Actual Dimension O.516' O.416' J. 8'6" O.068'	Accept		Method of			
Drawing Dimension 0.5 0.44 1.75 0.045	Min Min Min Min	Actual Dimension O.516' O.416' J. 8'6" O.068'	Accept		Method of			
Drawing Dimension 0.5 0.44 1.75 0.045	Min Min Min Min	Actual Dimension O.516' O.416' J. 8'6" O.068'	Accept		Method of			
Drawing Dimension 0.5 0.44 1.75 0.045	Min Min Min Min	Actual Dimension O.516' O.416' J. 8'6" O.068'	Accept		Method of			
Drawing Dimension 0.5 0.44 1.75 0.045	Min Min Min Min Min	Actual Dimension O.516' O.416' J. 8'6" O.068'	Accept		Method of	Comments		
Drawing Dimension 0.5 0.44 1.75 0.045 0.055	Min Min Min Min	Actual Dimension O.516' O.416' J. 8'6" O.068'	Accept		Method of Inspection	Comments		
Drawing	Min Min Min Min Min y:	Actual Dimension O.516' O.416' J. 8'6" O.068'	Accept		Method of Inspection	Comments 10/10/13		
Drawing Dimension 0.5 0.44 1.75 0.045 0.055 Measured by Audited by	Min Min Min Min Min y:	Actual Dimension O.56° O.46° I.56° O.068° O.068°	Accept		Method of Inspection Date:	Comments 10/10/13 N/A		

	•											
W/O:		WORK ORDER CHANGES										
DATE	STEP	PROCEDURE CHANGE				Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
	!		·									
Part No		PAR #:										
Resolution:				Disposition: Q			QA: N/C Closed:					
NCR:			WORK ORD	ER NON-CONFORM	ANCE (NCF	R)						
DATE	STEP	Description of NC			ion B	Verific	cation	Approval	Approval			
		Section A	Initial Chief Eng	Action Description Chief Eng	Sign 8 Date	Secti	on C	Chief Eng	QC Inspector			
					į							
							-					




Dart Aerospace Ltd	ospace Ltd
--------------------	------------

_										
W/O:			ORK ORDER CHANG	ES						
DATE	STEP	PR	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
								1		
Part No		PAR #:								
	Re			Disposition: Q/						
NCR:			WORK ORD	ER NON-CONFORMA	NCE (NC	R)				
DATE	STEP	Description of NC	Corrective Action Section B			Veritics		ation Approval A		
	0.2.	Section A	Initial Chief Eng	Action Description Chief Eng	Sign Dat		ion C	Chief Eng	QC Inspector	
								;		
									1	
							,			



	-										
W/O:		WORK ORDER CHANGES									
DATE	STEP	PROCEDURE CHANGE				Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
			- //								
Part No	:	PAR #:	Fault Cate	gory:	_ NCR: Yes	No DC	A:	Date:	· · · · · · · · · · · · · · · · · · ·		
Resolution:			Disposition: Q			QA: N/C Closed: Date: _					
NCR:			WORK ORDE	ER NON-CONFORM	ANCE (NC	R)					
DATE	STEP	Description of NC		ion B	Verif	cation	ation Approval	Approval			
	012.	Section A	Initial Chief Eng	Action Description Chief Eng	Sign Dat	& Sec	tion C	Chief Eng	QC Inspector		
						-					



W/O:			WORK ORDER CHANGES										
DATE	STEP	PRO	OCEDURE CHA	INGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
							7.7						
Part No) :	PAR #:	Fault Cate	gory:	_ NCR:	: Yes N	o DQA	:	_ Date: _				
			Disposition	Disposition: Q									
NCR:			WORK ORD	ER NON-CONFORMA	ANCE	(NCR)							
DATE	STEP	Description of NC	Corrective Action Initial Action Descripti		Section B n Sign &		Verification		Approval	Approval			
		Section A	Chief Eng	Chief Eng		Date	Sectio	n C	Chief Eng	QC Inspector			
							٠						
		•											
	ļ								**				